Device Script Updates 4/23/2021

The following device scripts have been updated with new features.

GPSI-5000

- 5000 (Diag) LD/HD/U (PEG Enable) (470) v4.6

- 5000 (HW) LD/HD/U (PEG Enable) (470) v4.6

  – Added ability to send DTC report when MIL lamp turns on
  – Updated realtime reporting functionality to reduce data usage
  – Added ability to send vehicle ID report with heartbeats
  – Updated default GPS sleep timer from 30 minutes to 5 minutes (ASK-1592)
  – Updated default Bluetooth setting to BLE Keyfob (was ELD Flex)

> **Note.** Please coordinate with our Support team to have your devices updated.

PNP-3100

- PNP – 4532-4562 (84a/.82/.43) v6.0.8 (435)

  – Updated default Bluetooth setting to BLE Keyfob
  – Resolved issue where Driver ID buzzer failed to buzz a full 30 minutes if the driver fails to press the BLE Keyfob driver assign button
  – Resolved issue where BLE Keyfob driver assignment will not send unless vehicle is Ignition On (ASK-1644)

> **Note.** Please coordinate with our Support team to have your devices updated.